

**APPENDIX E**

**References**

ANZG (2018). *Australian and New Zealand Guidelines for Fresh and Marine Water Quality*. Australian and New Zealand Governments and Australian state and territory governments, Canberra ACT, Australia.

Available at [www.waterquality.gov.au/anz-guidelines](http://www.waterquality.gov.au/anz-guidelines).

Cartwright N. and Nielsen P., (2001). Groundwater dynamics and salinity in coastal barriers. *Proc. SWICA-M<sup>3</sup>, 1<sup>st</sup> Intl. Conf. on Saltwater Intrusion and Coastal Aquifers - Monitoring, Modelling and Management*. (Essauira, Morocco), April 23-25, 2001.

enHealth (2012). Environmental Health Risk Assessment, Guidelines for assessing human health risks from environmental hazards, Commonwealth of Australia. Canberra. Available at [http://www.health.gov.au/internet/main/publishing.nsf/content/804F8795BABFB1C7CA256F1900045479/\\$File/DoHA-EHRA-120910.pdf](http://www.health.gov.au/internet/main/publishing.nsf/content/804F8795BABFB1C7CA256F1900045479/$File/DoHA-EHRA-120910.pdf).

Environmental Risk Sciences (EnRiskS) (2010). *Consolidated Human Health Risk Assessment – 2010*, 1 November 2010.

Environmental Risk Sciences (EnRiskS) (2012a). *Review of Risk Issues – Groundwater Discharge to Springvale Drain*, letter to Orica dated 1 June 2012.

Environmental Risk Sciences (EnRiskS) (2012b). *Review of Surface Water Criteria – Springvale*, letter to Orica dated 19 December 2012.

Environmental Risk Sciences (EnRiskS) (2018). *Consolidated Human Health Risk Assessment – 2017*, 16 March 2018.

Golder Associates Pty Ltd (2010a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2010*. Doc. No. 107623038-002-R-RevA-Monitoring Report, 31 May 2010.

Golder Associates Pty Ltd (2010b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2010*. Doc. No. 107623103-001-R-Rev0-Monitoring Report, 27 August 2010.

Golder Associates Pty Ltd (2010c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2010*. Doc. No. 107623138-001-R-Rev0-Monitoring Report, 30 November 2010.

Golder Associates Pty Ltd (2011a). *Conceptual Site Model – Botany*. Doc. No. 107623162-001-R-Rev0, 31 January 2011.

Golder Associates Pty Ltd (2011b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2010*. Doc. No. 107623177-001-R-Rev0-Monitoring Report, 12 June 2011.

Golder Associates Pty Ltd (2011c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2011*. Doc. No. 117623017-001-R-Rev0-Monitoring Report, 30 May 2011.

Golder Associates Pty Ltd (2011d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2011*. Doc. No. 117623046-001-R-Rev0-Monitoring Report, 31 August 2011.

Golder Associates Pty Ltd (2011e). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2011*. Doc. No. 117623087-001-R-Rev0-Monitoring Report, 30 November 2011.

Golder Associates Pty Ltd (2012a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2011*. Doc. No. 117623119-001-R-Rev0-Monitoring Report, 29 February 2012.

Golder Associates Pty Ltd (2012b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2012*. Doc. No. 127623015-001-R-Rev0-Monitoring Report, 31 May 2012.

Golder Associates Pty Ltd (2012c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2012*. Doc. No. 127623036-001-R-Rev0-Monitoring Report, 31 August 2012.

Golder Associates Pty Ltd (2012d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2012*. Doc. No. 127623148-001-R-Rev0-Monitoring Report, 30 November 2012.

Golder Associates Pty Ltd (2013a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2012*. Doc. No. 127623076-001-R-Rev0-Monitoring Report, 28 February, 2013.

Golder Associates Pty Ltd (2013b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2013*. Doc. No. 137623011-001-R-Rev0-Monitoring Report, 31 May, 2013.

Golder Associates Pty Ltd (2013c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2013*. Doc. No. 137623029-001-R-Rev0-Monitoring Report, 30 August, 2013.

Golder Associates Pty Ltd (2013d). *Groundwater Treatment Plant Groundwater and Surface Water Monitoring Program 2013 – 2016* Doc. No. 117623133-002-L-Rev1, 3 June, 2013.

Golder Associates Pty Ltd (2013e). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2013*. Doc. No. 137623048-001-R-Rev0-Monitoring Report, 30 November, 2013.

Golder Associates Pty Ltd (2014a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2013*. Doc. No. 147623002-001-R-Rev0-Monitoring Report, 28 February, 2014.

Golder Associates Pty Ltd (2014b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2014*. Doc. No. 147623013-001-R-Rev0-Monitoring Report, 30 May, 2014.

Golder Associates Pty Ltd (2014c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2014*. Doc. No. 147623029-001-R-Rev0-Monitoring Report, 29 August, 2014.

Golder Associates Pty Ltd (2014d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2014*. Doc. No. 147623068-001-R-Rev0-Monitoring Report, 30 November, 2014.

Golder Associates Pty Ltd (2015a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2014*. Doc. No. 1417383-001-R-Rev0-Monitoring Report, 27 February, 2015.

Golder Associates Pty Ltd (2015b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2015*. Doc. No. 1523540-001-R-Rev0-Monitoring Report, 29 May, 2015.

Golder Associates Pty Ltd (2015c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2015*. Doc. No. 1530977-001-R-Rev0, 31 August, 2015.

Golder Associates Pty Ltd (2015d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2015*. Doc. No. 1539153-001-R-Rev0, 30 November, 2015.

Golder Associates Pty Ltd (2016a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2015*. Doc. No. 1545097-001-R-Rev0-Monitoring Report, 29 February, 2016.

Golder Associates Pty Ltd (2016b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2016*. Doc. No. 1651194-001-R-Rev0-Monitoring Report, 31 May, 2016.

Golder Associates Pty Ltd (2016c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2016*. Doc. No. 1664279-001-R-Rev0-Monitoring Report, 31 August, 2016.

Golder Associates Pty Ltd (2016d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2016*. Doc. No. 1658163-001-R-Rev0-Monitoring Report, 30 November, 2016.

Golder Associates Pty Ltd (2017a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2016*. Doc. No. 1669818-001-R-Rev0- Monitoring Report, 29 February, 2017.

Golder Associates Pty Ltd (2017b). *Groundwater Treatment Plant, Groundwater and Surface Water Monitoring Program 2017-2020*, No. 127623052-TM-004-Rev1 dated 8 May 2017.

Golder Associates Pty Ltd (2017c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2017*. Doc. No. 1775769-001-R-Rev0- Monitoring Report, 31 May, 2017.

Golder Associates Pty Ltd (2017d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Biennial Groundwater and Surface Water Monitoring Report – September 2017*. Doc. No. 1786313-001-R-Rev0- Monitoring Report, 30 November, 2017.

Golder Associates Pty Ltd (2018a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Biannual Groundwater and Surface Water Monitoring Report – March 2018*. Doc. No. 1897402-001-R-Rev0- Monitoring Report, 29 May, 2018.

Golder Associates Pty Ltd (2018b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Annual Groundwater and Surface Water Monitoring Report – September 2018*. Doc. No. 18107271-001-R-Rev0- Monitoring Report, 30 November, 2018.

Golder Associates Pty Ltd (2019a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Biannual Groundwater and Surface Water Monitoring Report – March 2019*. Doc. No. 19118800-001-R-Rev0- Monitoring Report, 31 May, 2019.

Golder Associates Pty Ltd (2019b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant – September 2019 Biennial Groundwater and Surface Water Monitoring Report*. Doc. No. 19128956-001-R-Rev0- Monitoring Report, 6 December, 2019.

Golder Associates Pty Ltd (2020a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Biannual Groundwater and Surface Water Monitoring Report – March 2020*. Doc. No. 20139878-001-R-Rev0- Monitoring Report, 12 June, 2020.

Golder Associates Pty Ltd (2020b). *Groundwater Treatment Plant (GTP) Biannual Groundwater and Surface Water Monitoring Program 2020-2024*. Doc. No. 19135339-001-R-Rev0, 24 August, 2020.

JBS&G (2012). *Assessment of Hydraulic Containment, Botany Groundwater Cleanup Project, Botany NSW*. August 2012. JBS&G Environmental Pty Ltd.

JBS&G (2019). *2017 Assessment of Hydraulic Containment, Botany Groundwater Cleanup Project, Botany NSW*. November 2019. JBS&G Environmental Pty Ltd.

Laase, A.D. (2005) *Refinement of the Hydraulic Model for the Orica Groundwater Extraction System, Botany, NSW*, A.D. Laase Hydrologic Consulting. November 2005.

Laase, A.D. (2017) *Orica Botany Groundwater Extraction System Capture Performance Under Drought and Wet Conditions, Botany, NSW*, A.D. Laase Hydrologic Consulting. October 2017.

NEPC (1999 and 2013). National Environmental Protection (Assessment of Site Contamination) Measure 1999 and National Environment Protection (Assessment of Site Contamination) Amendment Measure 2013 (No.1).

Nielsen P., (1999). Groundwater Dynamics and Salinity in Coastal Barriers. *Journal of Coastal Research*. Vol. 15, No. 3, pp 732-740.

Orica Australia Pty Ltd (2010). Botany Groundwater Project - Groundwater Remediation and Management Plan. Document EN.1591.61.10.033. February 2010.

Orica Australia Pty Ltd (2017a). *Orica Botany Groundwater Cleanup Project – 2017 Botany Groundwater Strategy Review Workshop Summary Report - Orica Botany*. Report No. EN. 1591.61.PR074, Issued 28 April 2017.

Orica Australia Pty Ltd (2017b). Conceptual Site Model - Orica Botany, 2017. Version: Rev2, Issued 20 September 2017.

Orica Australia Pty Ltd (2020). Groundwater Remediation and Management Plan 2019-2024 – Botany Groundwater Cleanup Project. Document EN.1591.61.PR083. Rev 1. 26 March 2020.

Turner, I. L., Coates, B. P., & I. Acworth (1996). The effects of tides and waves on water-table elevations in coastal zones. *Hydrogeology Journal*, v. 4, No. 2, pp51-69.

URS (2004a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Cleanup Plan (GCP) Quarterly Groundwater and Surface Water Monitoring Report - March 2004*. Doc. No. R013\_A, 17 May 2004.

URS (2004b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Cleanup Plan (GCP) Quarterly Groundwater and Surface Water Monitoring Report - June 2004*. Doc. No. R018\_A, 19 August 2004.

URS (2004c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Cleanup Plan (GCP) Quarterly Groundwater and Surface Water Monitoring Report - September 2004*. Doc. No. R019\_A, 17 November 2004.

URS (2004d). *Botany Groundwater Cleanup Project - Environmental Impact Statement (EIS)*. Prepared for Orica Australia Pty Ltd, 12 November 2004.

URS (2005a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Cleanup Plan (GCP) Quarterly Groundwater and Surface Water Monitoring Report - December 2004*. Doc. No. R021\_A, 15 February 2005.

URS (2005b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Cleanup Plan (GCP) Quarterly Groundwater and Surface Water Monitoring Report - March 2005*. Doc. No. R025\_A, 17 May 2005.

URS (2005d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Cleanup Plan (GCP) Quarterly Groundwater and Surface Water Monitoring Report - June 2005*. Doc. No. R028, 15 August 2005.

URS (2005e). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant - Groundwater and Surface Water Monitoring Program (Draft)*. Doc. No. R027, 15 July 2005.

URS (2005f). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - September 2005*. Doc. No. R029, 30 November 2005.

URS (2006a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - December 2005*. Doc. No. Rev C, 28 June 2006.

URS (2006c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - March 2006*. Doc. No. R02, 31 May 2006.

URS (2006d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - June 2006*. Doc. No. R03, 31 August 2006.

URS (2006e). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - September 2006*. Doc. No. R02, 30 November 2006.

URS (2007a). WCIE-4341 Orica Botany Environmental Survey, Stage 4 – Remediation. *Amended GTP Groundwater and Surface Water Monitoring Program*. Letter Report. 8 January 2007

URS (2007b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - December 2006*. Doc. No. R02, 28 February 2007.

URS (2007c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - March 2007*. Doc. No. R03, 31 May 2007.

URS (2007d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - June 2007*. Doc. No. R03, 31 August 2007.

URS (2007e). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - September 2007*. Doc. No. R02, 30 November 2007.

URS (2008a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2007*. Doc. No. R01, 29 February 2008.

URS (2008b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2008*. Doc. No. R01, 30 May 2008.

URS (2008c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2008*. Doc. No. 43217830, 29 August 2008.

URS (2008d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2008*. Doc. No. 43217860, 28 November 2008.

URS (2008e). *Surface Water and Ambient Air Monitoring for Springvale Drain*. Prepared for Orica Australia Pty Ltd, 12 December 2008.

URS (2009a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2008*. Doc. No. 43217910, 20 February 2009.

URS (2009b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2009*. Doc. No. 43217960, 26 May 2009.

URS (2009c). Orica Botany Environmental Survey, Stage 4 – Remediation. *WWCIE 4446 Calculation of Weighted Air Concentration near Springvale Drain*. Doc. No. 43218021, 11 August 2009.

URS (2009d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2009*. Doc. No. 43218011, 31 August 2009.

URS (2009e). *GTP Groundwater and Surface Water Monitoring Program, 2008 – 2010*. Doc. No. WCIE 4447, 28 October 2009.

URS (2009f). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2009*. Doc. No. 43218078, 30 November 2009.

URS (2010a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2009*. Doc. No. 43218116, 26 February 2010.

USEPA (2008a). USEPA Contract Laboratory Program. *National Functional Guidelines for Superfund Organic Methods Data Review*. Office of Superfund Remediation and Technology Innovation. Publication EPA540/R-08-01, June 2008.

USEPA (2008b). *A Systematic Approach for the Evaluation of Capture Zones at Pump and Treat Systems* by United States Environment Protection Agency (USEPA, 2008b).