

Appendix E

References

ANZG (2018). *Australian and New Zealand Guidelines for Fresh and Marine Water Quality*. Australian and New Zealand Governments and Australian state and territory governments, Canberra ACT, Australia. Available at www.waterquality.gov.au/anz-guidelines.

Cartwright N. and Nielsen P., (2001). Groundwater dynamics and salinity in coastal barriers. *Proc. SWICA-M³, 1st Intl. Conf. on Saltwater Intrusion and Coastal Aquifers - Monitoring, Modelling and Management*. (Essauira, Morocco), April 23-25, 2001.

enHealth (2012). *Environmental Health Risk Assessment, Guidelines for assessing human health risks from environmental hazards*, Commonwealth of Australia. Canberra. Available at [http://www.health.gov.au/internet/main/publishing.nsf/content/804F8795BABFB1C7CA256F1900045479/\\$File/DoHA-EHRA-120910.pdf](http://www.health.gov.au/internet/main/publishing.nsf/content/804F8795BABFB1C7CA256F1900045479/$File/DoHA-EHRA-120910.pdf).

Environmental Risk Sciences (EnRiskS) (2010). *Consolidated Human Health Risk Assessment – 2010*, 1 November 2010.

Environmental Risk Sciences (EnRiskS) (2012a). *Review of Risk Issues – Groundwater Discharge to Springvale Drain*, letter to Orica dated 1 June 2012.

Environmental Risk Sciences (EnRiskS) (2012b). *Review of Surface Water Criteria – Springvale*, letter to Orica dated 19 December 2012.

Environmental Risk Sciences (EnRiskS) (2018). *Consolidated Human Health Risk Assessment – 2017*, 16 March 2018.

Golder Associates Pty Ltd (2010a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2010*. Doc. No. 107623038-002-R-RevA-Monitoring Report, 31 May 2010.

Golder Associates Pty Ltd (2010b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2010*. Doc. No. 107623103-001-R-Rev0-Monitoring Report, 27 August 2010.

Golder Associates Pty Ltd (2010c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2010*. Doc. No. 107623138-001-R-Rev0-Monitoring Report, 30 November 2010.

Golder Associates Pty Ltd (2011a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2010*. Doc. No. 107623177-001-R-Rev0-Monitoring Report, 12 June 2011.

Golder Associates Pty Ltd (2011b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2011*. Doc. No. 117623017-001-R-Rev0-Monitoring Report, 30 May 2011.

Golder Associates Pty Ltd (2011c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2011*. Doc. No. 117623046-001-R-Rev0-Monitoring Report, 31 August 2011.

Golder Associates Pty Ltd (2011d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2011*. Doc. No. 117623087-001-R-Rev0-Monitoring Report, 30 November 2011.

Golder Associates Pty Ltd (2012a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2011*. Doc. No. 117623119-001-R-Rev0-Monitoring Report, 29 February 2012.

Golder Associates Pty Ltd (2012b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2012*. Doc. No. 127623015-001-R-Rev0-Monitoring Report, 31 May 2012.

Golder Associates Pty Ltd (2012c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2012*. Doc. No. 127623036-001-R-Rev0-Monitoring Report, 31 August 2012.

Golder Associates Pty Ltd (2012d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2012*. Doc. No. 127623148-001-R-Rev0-Monitoring Report, 30 November 2012.

Golder Associates Pty Ltd (2013a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2012*. Doc. No. 127623076-001-R-Rev0-Monitoring Report, 28 February 2013.

Golder Associates Pty Ltd (2013b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2013*. Doc. No. 137623011-001-R-Rev0-Monitoring Report, 31 May 2013.

Golder Associates Pty Ltd (2013c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2013*. Doc. No. 137623029-001-R-Rev0-Monitoring Report, 30 August 2013.

Golder Associates Pty Ltd (2013d). *Groundwater Treatment Plant Groundwater and Surface Water Monitoring Program 2013 – 2016* Doc. No. 117623133-002-L-Rev1, 3 June 2013.

Golder Associates Pty Ltd (2013e). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2013*. Doc. No. 137623048-001-R-Rev0-Monitoring Report, 30 November 2013.

Golder Associates Pty Ltd (2014a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2013*. Doc. No. 147623002-001-R-Rev0-Monitoring Report, 28 February 2014.

Golder Associates Pty Ltd (2014b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2014*. Doc. No. 147623013-001-R-Rev0-Monitoring Report, 30 May 2014.

Golder Associates Pty Ltd (2014c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2014*. Doc. No. 147623029-001-R-Rev0-Monitoring Report, 29 August 2014.

Golder Associates Pty Ltd (2014d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2014*. Doc. No. 147623068-001-R-Rev0-Monitoring Report, 30 November 2014.

Golder Associates Pty Ltd (2015a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2014*. Doc. No. 1417383-001-R-Rev0-Monitoring Report, 27 February 2015.

Golder Associates Pty Ltd (2015b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2015*. Doc. No. 1523540-001-R-Rev0-Monitoring Report, 29 May 2015.

Golder Associates Pty Ltd (2015c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2015*. Doc. No. 1530977-001-R-Rev0, 31 August 2015.

Golder Associates Pty Ltd (2015d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2015*. Doc. No. 1539153-001-R-Rev0, 30 November 2015.

Golder Associates Pty Ltd (2016a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2015*. Doc. No. 1545097-001-R-Rev0-Monitoring Report, 29 February 2016.

Golder Associates Pty Ltd (2016b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2016*. Doc. No. 1651194-001-R-Rev0-Monitoring Report, 31 May 2016.

Golder Associates Pty Ltd (2016c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2016*. Doc. No. 1664279-001-R-Rev0-Monitoring Report, 31 August 2016.

Golder Associates Pty Ltd (2016d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2016*. Doc. No. 1658163-001-R-Rev0-Monitoring Report, 30 November 2016.

Golder Associates Pty Ltd (2017a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2016*. Doc. No. 1669818-001-R-Rev0- Monitoring Report, 29 February 2017.

Golder Associates Pty Ltd (2017b). *Groundwater Treatment Plant, Groundwater and Surface Water Monitoring Program 2017-2020*, No. 127623052-TM-004-Rev1 dated 8 May 2017.

Golder Associates Pty Ltd (2017c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2017*. Doc. No. 1775769-001-R-Rev0- Monitoring Report, 31 May 2017.

Golder Associates Pty Ltd (2017d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Biennial Groundwater and Surface Water Monitoring Report – September 2017*. Doc. No. 1786313-001-R-Rev0- Monitoring Report, 30 November 2017.

Golder Associates Pty Ltd (2018a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Biannual Groundwater and Surface Water Monitoring Report – March 2018*. Doc. No. 1897402-001-R-Rev0- Monitoring Report, 29 May 2018.

Golder Associates Pty Ltd (2018b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Annual Groundwater and Surface Water Monitoring Report – September 2018*. Doc. No. 18107271-001-R-Rev0- Monitoring Report, 30 November 2018.

Golder Associates Pty Ltd (2019a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Biannual Groundwater and Surface Water Monitoring Report – March 2019*. Doc. No. 19118800-001-R-Rev0- Monitoring Report, 31 May 2019.

- Golder Associates Pty Ltd (2019b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant – September 2019 Biennial Groundwater and Surface Water Monitoring Report*. Doc. No. 19128956-001-R-Rev0- Monitoring Report, 6 December 2019.
- Golder Associates Pty Ltd (2020a). Groundwater Treatment Plant (GTP) Biannual Groundwater and Surface Water Monitoring Program 2020-2024. Doc. No. 19135339-001-R-Rev0, 24 August 2020.
- Golder Associates Pty Ltd (2020b). Orica Botany Environmental Survey, Stage 4 – Remediation. Groundwater Treatment Plant (GTP) Biannual Groundwater and Surface Water Monitoring Report – March 2020. Doc. No. 20139878-001-R-Rev0- Monitoring Report, 12 June 2020.
- Golder Associates Pty Ltd (2020c). Orica Botany Environmental Survey, Stage 4 – Remediation. Groundwater Treatment Plant (GTP) Annual Groundwater and Surface Water Monitoring Report – September 2020. Doc. No. 20359032-001-R-Rev0, 30 November 2020.
- JBS&G (2012). *Assessment of Hydraulic Containment, Botany Groundwater Cleanup Project, Botany NSW*. August 2012. JBS&G Environmental Pty Ltd.
- JBS&G (2019). *2017 Assessment of Hydraulic Containment, Botany Groundwater Cleanup Project, Botany NSW*. November 2019. JBS&G Environmental Pty Ltd.
- Laase, A.D. (2005) *Refinement of the Hydraulic Model for the Orica Groundwater Extraction System, Botany, NSW*, A.D. Laase Hydrologic Consulting. November 2005.
- Laase, A.D. (2017) *Orica Botany Groundwater Extraction System Capture Performance Under Drought and Wet Conditions, Botany, NSW*, A.D. Laase Hydrologic Consulting. October 2017.
- NEPC (2013). National Environmental Protection (Assessment of Site Contamination) Measure .
- Nielsen P., (1999). Groundwater Dynamics and Salinity in Coastal Barriers. *Journal of Coastal Research*. Vol. 15, No. 3, pp 732-740.
- Orica Australia Pty Ltd (2010). Botany Groundwater Project - Groundwater Remediation and Management Plan. Document EN.1591.61.10.033. February 2010.
- Orica Australia Pty Ltd (2017a). *Orica Botany Groundwater Cleanup Project – 2017 Botany Groundwater Strategy Review Workshop Summary Report - Orica Botany*. Report No. EN. 1591.61.PR074, Issued 28 April 2017.
- Orica Australia Pty Ltd (2017b). Conceptual Site Model - Orica Botany, 2017. Version: Rev2, Issued 20 September 2017.
- Orica Australia Pty Ltd (2020). Groundwater Remediation and Management Plan 2019-2024 – Botany Groundwater Cleanup Project. Document EN.1591.61.PR083. Rev 1. 26 March 2020.
- Turner, I. L., Coates, B. P., & I. Acworth (1996). The effects of tides and waves on water-table elevations in coastal zones. *Hydrogeology Journal*, v. 4, No. 2, pp51-69.
- URS (2004a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Cleanup Plan (GCP) Quarterly Groundwater and Surface Water Monitoring Report - March 2004*. Doc. No. R013_A, 17 May 2004.
- URS (2004b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Cleanup Plan (GCP) Quarterly Groundwater and Surface Water Monitoring Report - June 2004*. Doc. No. R018_A, 19 August 2004.

URS (2004c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Cleanup Plan (GCP) Quarterly Groundwater and Surface Water Monitoring Report - September 2004*. Doc. No. R019_A, 17 November 2004.

URS (2004d). *Botany Groundwater Cleanup Project - Environmental Impact Statement (EIS)*. Prepared for Orica Australia Pty Ltd, 12 November 2004.

URS (2005a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Cleanup Plan (GCP) Quarterly Groundwater and Surface Water Monitoring Report - December 2004*. Doc. No. R021_A, 15 February 2005.

URS (2005b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Cleanup Plan (GCP) Quarterly Groundwater and Surface Water Monitoring Report - March 2005*. Doc. No. R025_A, 17 May 2005.

URS (2005c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Cleanup Plan (GCP) Quarterly Groundwater and Surface Water Monitoring Report - June 2005*. Doc. No. R028, 15 August 2005.

URS (2005d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant - Groundwater and Surface Water Monitoring Program (Draft)*. Doc. No. R027, 15 July 2005.

URS (2005e). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - September 2005*. Doc. No. R029, 30 November 2005.

URS (2006a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - December 2005*. Doc. No. Rev C, 28 June 2006.

URS (2006b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - March 2006*. Doc. No. R02, 31 May 2006.

URS (2006c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - June 2006*. Doc. No. R03, 31 August 2006.

URS (2006d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - September 2006*. Doc. No. R02, 30 November 2006.

URS (2007a). WCIE-4341 Orica Botany Environmental Survey, Stage 4 – Remediation. *Amended GTP Groundwater and Surface Water Monitoring Program*. Letter Report. 8 January 2007

URS (2007b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - December 2006*. Doc. No. R02, 28 February 2007.

URS (2007c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - March 2007*. Doc. No. R03, 31 May 2007.

URS (2007d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - June 2007*. Doc. No. R03, 31 August 2007.

- URS (2007e). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report - September 2007*. Doc. No. R02, 30 November 2007.
- URS (2008a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2007*. Doc. No. R01, 29 February 2008.
- URS (2008b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2008*. Doc. No. R01, 30 May 2008.
- URS (2008c). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2008*. Doc. No. 43217830, 29 August 2008.
- URS (2008d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2008*. Doc. No. 43217860, 28 November 2008.
- URS (2009a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2008*. Doc. No. 43217910, 20 February 2009.
- URS (2009b). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – March 2009*. Doc. No. 43217960, 26 May 2009.
- URS (2009c). Orica Botany Environmental Survey, Stage 4 – Remediation. *WWCIE 4446 Calculation of Weighted Air Concentration near Springvale Drain*. Doc. No. 43218021, 11 August 2009.
- URS (2009d). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – June 2009*. Doc. No. 43218011, 31 August 2009.
- URS (2009e). *GTP Groundwater and Surface Water Monitoring Program, 2008 – 2010*. Doc. No. WCIE 4447, 28 October 2009.
- URS (2009f). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – September 2009*. Doc. No. 43218078, 30 November 2009.
- URS (2010a). Orica Botany Environmental Survey, Stage 4 – Remediation. *Groundwater Treatment Plant (GTP) Quarterly Groundwater and Surface Water Monitoring Report – December 2009*. Doc. No. 43218116, 26 February 2010.
- USEPA (2008a). USEPA Contract Laboratory Program. *National Functional Guidelines for Superfund Organic Methods Data Review*. Office of Superfund Remediation and Technology Innovation. Publication EPA540/R-08-01, June 2008.
- USEPA (2008b). *A Systematic Approach for the Evaluation of Capture Zones at Pump and Treat Systems* by United States Environment Protection Agency (USEPA, 2008b).